











1.1

HUS-H	$h_{nom}$	$h_1$	$t_{fix}$
8x80	75 mm	90 mm - $t_{fix}$	0 ... 5 mm
8x90	75 mm	100 mm - $t_{fix}$	0 ... 15 mm
8x110	75 mm	120 mm - $t_{fix}$	0 ... 35 mm
8x130	75 mm	140 mm - $t_{fix}$	0 ... 55 mm
8x150	75 mm	160 mm - $t_{fix}$	0 ... 75 mm





















2.1

			
			
$d_0$	Ø 8 mm	Ø 8 mm	Ø 6 mm



4.1

			
	SIW 14-A		
	SIW 22-A		
	SIW 22T-A		
	SI 100		
	45 Nm		

4.2

